



AOG Reaction
526 Aviator Drive
Fort Worth, TX 76179-5425

• F.A.A. REPAIR STATION TU1R519K
(817) 439-0700
FAX: (817) 439-9700

REPAIRABLE PART

Part Nomenclature Transducer Customer Airmark Intl
308162
Manufacturer Crane, Hydro Aire Division Work Order # 124212
S/N 3943 Part # 40-911
Remarks FUNCTIONAL TESTED OK.
EXCESSIVE END PLAY
RETURNED AS IS AT CUSTOMER REQUEST
Authorized Signature [Signature] Date 8/26/2009