



# SERVICEABLE

MFR. NAME GINI  
COMPONENT NAME Omega  
MODEL NO. 10864-1  
SERIAL NO. 2026

The component identified above was repaired, serviced and tested in accordance with current regulations of The Federal Aviation Agency and is approved for return to service.

Details of the repair are on file at this maintenance station.

WORK ORDER NO. 5071  
DATE 4-25-79  
SIGNED [Signature]



**Global  
Navigation  
Incorporated**

24701 Crenshaw Boulevard  
Torrance, California 90505

FAA MMF 465-44