



AERO SKY
2030 First Avenue, Hangar 4
San Antonio International Airport
San Antonio, Texas 78216
FAA Approved Repair Station No. K27R556N

REJECTED PARTS TAG

Registration N:4629

Work Order No. 5783012-2

Date MAY 6 2014

Manufacturer Boeing

Identification #1 EWL 9 o'clock igniter

Part Number 9072215-1

Serial Number JVL129

Qty 1

TSO

Location

#1 EWL

Discrepancy Cracking damage, burned

inside.

Rejected by Inspector (Printed Name) _____

Signature _____