

CONFIGURATION MODULE
P/N 17680-01
REF. ENG. DWG. 400-017680

WT: 1 LB
TSO-C115a

S/N **316**

MOD

1	2	3	4
---	---	---	---

AlliedSignal Avionics Inc.
PRESCOTT, ARIZONA U.S.A.

WARN
WARRANT
WHEN TH
IS BRO

300-317603-71 REV. B
23720
GMDD

GNS-X/ES
P/N 17450-0101
REF. ENG. DWG. 400-017450

OPTIONS	S/N	WT	LBS
0002	212	9.8	

HARDWARE MODS
1 2 3 4 5 6 7 8
9 10 11 12 13 14 15 16

THIS LRU CAN BE REPLACED WITH AN LRU HAVING THE SAME SET OF HARDWARE MODS. ADDITIONAL MODS ARE ACCEPTABLE.

SOFTWARE MODS
1 2 3 4 5 6 7 8
9 10 11 12 13 14 15 16
17 18 19 20 21 22 23 24
25 26 27 28 29 30 31 32

THIS LRU CAN BE REPLACED WITH AN LRU OF THE SAME MOD STATUS, OR HIGHER NUMBER SOFTWARE MOD STATUS.


Software Level = 2

AlliedSignal Avionics Inc.
PRESCOTT, ARIZONA 86301 U.S.A.

TSO-C115a

DO-160C ENVIRONMENTAL CATEGORIES
[D1F1] VBA-(MNB) E1 XXXXX ZAAZZRZKXX

SEP 00 2003
14
T
T
CRL



MNE-CJU Maintenance Center (B03)

SERVICEABLE

MOLIT Certificate Number

2004-AMO-A01

Instance Number 1414499	Manufacturer 27007	Preservation Maintenance		
Description CONTROL DISPLAY UNIT		Complete Date YYYY-MM-DD	Due Date YYYY-MM-DD	Inspector
Part Number 17450-0101-0002	Storage Limit Control N/L	YYYY-MM-DD	YYYY-MM-DD	
Serial Number 212	Quantity -1-	YYYY-MM-DD	YYYY-MM-DD	
Service Date YYYY-MM-DD 2019-10-21	TSO/CSO 7937/25802	Hard Time Control Part Date Only		
Technician JS오정기 2004065	RTS/Inspector JSG 08	Manufacture Date YYYY-MM-DD	HYD Test Date YYYY-MM-DD	Restoration Date YYYY-MM-DD
PO/Work Order No 26417604	Status/Work -Z-	Remarks (Removal ID) 1769798		
Serviceable Removed From				
A/C Type (or NHA P/N) CTN-AC	A/C No (or NHA S/N) HL7501			
Position CTN_3450 CONTROL DISPLAY UNIT-FMS_LH				

(Blank) Rotable

Removal / Installation Status

Removed Part Number ONLY	Work Order Number 26417372	Removal Reason <input type="checkbox"/> 11 Time Limit <input type="checkbox"/> 12 For Modification <input type="checkbox"/> 13 Convenience <input type="checkbox"/> 21 Flight Defect <input type="checkbox"/> 22 Maintenance Defect <input type="checkbox"/> 30 Other Reason <input type="checkbox"/> 31 New Arrival <input type="checkbox"/> 32 Back From Vendor <input type="checkbox"/> 33 NHA Disassembly <input type="checkbox"/> 34 Store Limits <input type="checkbox"/> 35 Store Failure <input type="checkbox"/> 37 Preservation Maintenance <input type="checkbox"/> 38 Loan Return <input type="checkbox"/> 39 SAVE <input type="checkbox"/> 40 NFF Evaluation <input type="checkbox"/> 41 Cannibalization <input type="checkbox"/> 42 Swap <input type="checkbox"/> 43 Interchange
Removed Serial Number ONLY	Quantity -1-	
A/C Type (or NHA Part Number) CTN-AC	Station B03	
A/C Number (or NHA Serial Number) HL7502	Department OTJ	
Position LH		
Removal / Install Date YYYY-MM-DD 2019-10-21	Technician JS오정기 2004065	Inspector JSG 08
Failure Description N/A		

64