


1. Approving Civil Aviation Authority/Country: F.A.A./United States	2. <b>AUTHORIZED RELEASE CERTIFICATE</b>			3. Form Tracking Number: 25-30768
4. Organization Name and Address: OBrien Enterprises - 2420 East 28th St. - Signal Hill CA 90755 (QK3R792L)				5. Work Order/Contract/Invoice Number: 29798
6. Item: 1	7. Description: Fire extinguisher	8. Part Number: 32700015	9. Quantity: 1	10. Serial Number: 14447 CI
11. Status/Work: Overhauled				
12. Remarks:  Overhauled in accordance with approved data, CMM 26-20-202, REV 08-01-2019 Inspect, clean, hydrostatic test, repair as required, refill and leak test. Cartridge Info: P/N AE 13083-5, Serial # 1122, D.O.M. 09-2019 AE 13083-5, Serial # A7301 D.O.M. 8-2025 Inspect and test pressure switch: N/A Other P/N: N/A				
Last Overhaul 09-27-2025 Next overhaul due 09-27-2030				
13a. Certifies the items identified above were manufactured in conformity to:  <input type="checkbox"/> Approved design data and are in a condition for safe operation. <input type="checkbox"/> Non-approved design data specified in Block 12.		14a. <input type="checkbox"/> 14 CFR 43.9 Return to Service <input type="checkbox"/> Other regulation specified in Block 12  Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.		
13b. Authorized Signature: XXXXXXXXXXXXXXXXXXXXXXXXXXXX	13c. Approval/Authorization No.: XXXXXXXXXXXXXXXXXXXXXX	14b. Authorized Signature: 	14c. Approval/Certificate No.: QK3R792L	
13d. Name (Typed or Printed): XXXXXXXXXXXXXXXXXXXXXXXXXXXX	13e. Date (dd/mm/yy): XXXXXXXXXXXXXXXXXXXXXXXXXXXX	14d. Name (Typed or Printed): Sid OBrien	14e. Date (dd/mm/yy): 18NOV2025	
<b>User/Installer Responsibilities</b>				
<p>It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.</p> <p>Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.</p> <p>Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.</p>				

X X

**O'Brien Enterprises**

2420 E. 28th Street, Unit 2  
Signal Hill, California 90755  
Tel: 562-988-9546  
Email: sobrienenterprises@gmail.com  
F.A.A. # QK3R792L

WORK ORDER NO. 29798

**INSPECTION AND TEARDOWN REPORT**

Customer Pius Parts Date Received 24SEP2025  
Address Rockport TX Units Received this P.O. 2  
Customer P.O. # P00673 Unit 1 of 2 Units  
Part Number 32700015 Assembly Serial # 14447 C1  
Other Part Number N/A Cylinder Serial # \_\_\_\_\_  
Manufacturer: Kidde  HTL/PacSci  AMEREX  Other \_\_\_\_\_  
Description: Fire Extinguisher  Other \_\_\_\_\_

**CUSTOMER REQUESTS**

Overhaul  Weight and Leak Test   
Hydrostatic Test  Inspect interior   
Repair  Other \_\_\_\_\_  
Refill  Inspect and test pressure switch Yes  No  N/A

\* **INITIAL INSPECTION**

Date of Mfg. 08-1995 DOT Rating: 4D 7945-700 Other \_\_\_\_\_  
Last Overhaul 06-2020 Capacity: 60 C.I.  86 C.I.  90 C.I.  125 C.I.   
#1 Cartridge Date: 09/2019 None  195 C.I.  224 C.I.  Other Cap. \_\_\_\_\_  
#2 Cartridge Date: 09/2019 None  Test P.S.I. 1600  1800  2000  2100  2400  3000  Other \_\_\_\_\_  
#3 Cartridge Date: \_\_\_\_\_ / \_\_\_\_\_ None  Received: Full  Empty  Fired  Low P.S.I.

**INITIAL INSPECTION ANALYSIS**

Parts Missing: None  Cartridge(s)  Discharge Outlet(s)  Safety Cap(s)  Halon/N2  Other: \_\_\_\_\_  
Additional Parts Received: None  Safety Caps  Strap/Clamp  Other \_\_\_\_\_  
Exterior Condition: Good  Fair  Poor  Other 1 cartridge damaged in transit  
Interior Inspection: Pass  Fail  Hidden Damage: Yes  No  Comment: \_\_\_\_\_

Repairable: Yes  No  BER/Scrap: Yes  No   
Serviced per Mfg: HTL/PacSci  Kidde  NFPA10  Other \_\_\_\_\_  
Serviced I.A.W. Customer Procedures Manual: Yes  No  Manual # 26-20-202 Rev. Date 08-01-2020  
Other \_\_\_\_\_ Rev. # 8-1-2019  
Investigate A.D. Activity: Yes  No  By Sid O Findings: No Activity  Other: \_\_\_\_\_

**CORRECTIVE ACTIONS**

Overhauled IAW Mfg Specs  Inspect Interior  Scope of Work: Inspect and test pressure switch Yes  No  N/A  
Repaired IAW Mfg Specs  Refinish Exterior   
Recharge - Wt. and/or Leak Test  No Work Done   
Hydrostatic Test IAW DOT/CFR49, PART 180.2