

O'Brien Ent.
562-988-9546

11	B5	25
MO	82	YR

Signal Hill, CA

NEXT HYDRO DUE

YEAR	2028	MO	11
------	------	----	----

O'BRIEN ENTERPRISES
Signal Hill, CA
562-988-9546



O'Brien Enterprises

2420 E. 28th Street, Suite 2
Signal Hill, California 90755
Tel: 562-988-9546
Email: sobrienenterprises@gmail.com

WORK ORDER NO. **HY 27613**
D.O.T. #B528

HYDROSTATIC TEST FINDINGS AND COMPLETION REPORT

Customer Pius Parts Date Received 11-14-2025
Address Rockport Units Received this P.O. 1
P.O. # P00756 Unit 1 of 1 Units. Page 1 of 2 Pages
Mfg. Part Number 212940-2 Assembly Serial # 8764
Other Part Number 9912103-3 Cylinder Serial # 72319 B1
Valve P/N # _____
Valve(s) Serial # _____
Manufacturer:
Kidde HTL/PacSci Scott Puritan B/E Tavco Av-0x Sota
Aerox Precise Flight ITT _____ Other _____
Description: 02 Cylinder N2 Cylinder Other _____

REASON FOR RETURN

Hydrostatic Test Other: _____
Repair _____
Recharge _____
Service Regulator _____

INITIAL INSPECTION

Date of Mfg: 07-2015 Size: 90 C.F. TEST PRESSURE 4800 P.S.I.
Last Hydro: 03-2022 C.I. Other Information: _____
DOT Rating: _____
8162-1850 Non-DOT Cylinder
3AA1800 Other _____ Full
3HT1850 Empty
10945-1850
3AL _____

Parts Missing: None Safety Cap(s) Valve(s) Fittings 3 Other: _____
Additional Parts Received: None Safety Caps Strap/Clamp Mask Other: _____
Exterior Condition: Good Fair Poor Comments: _____
Interior Inspection: Pass Fail Hidden Damage: None Comments: _____

Repairable: Yes No BER/Scrap: Yes No
Serviced per Mfg: HTL/PacSci Kidde DOT/CFR49 Other: _____
Serviced I.A.W. Customer Procedures Manual: Yes No Manual # 36-10-03 Rev. 11/03
Other: _____

CORRECTIVE ACTION

Hydrostatic Test Repaired Scope of Work: _____
Inspect Interior Recharge _____
Refinish Ext. No Work Done _____
Wt. and/or Leak Test Inspect and Condemn _____